

RECEIVED  
NOV 14 1990

DIVISION OF  
OIL, GAS & MINING

3809  
UT-086  
UMC-284167

CERTIFIED MAIL  
Return Receipt Requested  
No. P 104 699 088

NOV 13 1990

Mr. Dale Stevens  
Box 1343  
Vernal, UT 84078

Dear Mr. Stevens:

My letter of 11/06/90 regarding conditions on the Rainbow #1 claim was refused and, subsequently, returned to me. This letter serves as a second attempt to correspond to you regarding some surface management issues which require your attention.

On our most recent inspection (August 16, 1990) of your mine operation on your Rainbow #1 claim, UMC-284167, it was apparent that your operation there has remained inactive since at least July 26, 1989. Under the stipulations attached to your Notice of Intent of September 29, 1990, you are required to reclaim your site where "...no evidence of valuable mineralization is revealed by trenching or shafts...". You will also note that in your addendum to your Notice of Intent you agreed to take measures to prevent animals and people from falling into your mine shaft during periods of non-operation. As of August 16, 1990, this has not been done.

If you plan to continue operations at this site, you should take immediate measures to fence the shaft there. Fencing should meet the following standards:

- a. 39-inch net wire shall be used with at least one strand of barbed wire on top of the net wire (barbed wire is not necessary if pipe or some type of reinforcement rod is attached to the top of the entire fence).
- b. The net wire shall be no more than 2-inches above the ground. The barbed wire shall be 3-inches above the net wire. Total height of the fence shall be at least 42-inches.
- c. Corner posts shall be cemented and/or braced in such a manner to keep the fence tight at all times.


- d. Standard steel, wood or pipe posts shall be used between the corner braces. Maximum distance between any two posts shall be no greater than 16 feet.
- e. All wire shall be stretched, by using a stretching device, before it is attached to the corner posts.

If you do not plan to conduct any further operations at the site, you should reclaim the site immediately.

Failure to comply with the provisions of a Notice of Intent usually leads the BLM to issue a formal Notice of Non-compliance. Such a notice would require the operator to come into compliance within strict time frames. An operator with an established record of non-compliance would be required to submit Mining Plans of Operation and would also be required to post a bond prior to commencing future operations.

If you have any questions regarding this please call feel free to call me here at (801) 789-1362.

Sincerely,



Ronald S. Trogstad  
Area Manager  
Diamond Mountain Resource Area

cc: Holland Sheppard  
Utah DOGM